

Link do produktu: <https://www.strefainternetowa.com/obuwie-robocze-buty-wysokie-schmith-safe-extreme-rozmiar-41-p-1830.html>



Obuwie robocze buty wysokie Schmith SAFE EXTREME rozmiar 41

Cena	371,00 zł
Numer katalogowy	ALP-18063490361
Kod producenta	SCH13S02041
Kod EAN	5902004776545

Opis produktu

Buty robocze, zapewniające maksymalną ochronę i funkcjonalność podczas pracy w każdych warunkach. Posiadają nowoczesny, stylowy design który sprawia, że nadają się do noszenia również na co dzień.

Cechy butów roboczych SAFE EXTREME 2:

- Klasa bezpieczeństwa S3L
- Obuwie przeznaczone do najbardziej wymagających prac w najcięższych warunkach
- Cholewka zeskóry naturalnej, nubuku najwyższej jakości
- Wzmocniony podnosek z kompozytu, chroniący palce przed uderzeniem do 200J
- Antyprzebiciowa wkładka z kevlaru, lekkiego i elastycznego materiału odpornego na przebicia
- Antypoślizgowa, olejoodporna podeszwa o właściwościach antyelektrostatycznych, wykonana z materiałów PU/TPU
- Podeszwa zawiera specjalne wypusty niwelujące ryzyko poślizgnięcia
- Technologia absorpcji energii w części piętowej
- Niewielka masa własna butów, umożliwia długie ich noszenie bez zmęczenia stóp
- Wymienna, absorbująca wkładka LIFHT DOAM, wykonana z bardzo miękkiej pianki poliuretanowej
- Oddychająca, antybakteryjna podeszwa, odporna na wytarcia i doskonale odprowadzająca wilgoć

Parametry produktu

- **Stan:** Nowy
- **Kod producenta:** SCH13S02041

-
- **Marka:** Schmith
 - **Model:** SAFE EXTREME
 - **Rozmiar obuwia:** 41
 - **Rodzaj buta:** buty wysokie
 - **Przeznaczenie:** uniwersalne
 - **Kategoria ochrony buta:** S3
 - **Cechy dodatkowe:** z podnoskiem
 - **EAN (GTIN):** 5902004776545

Informacje o bezpieczeństwie

List of safety warnings for work boots based on the requirements of General Product Safety Regulation (EU) 2023/988 (GPSR):

1. Make sure your shoes are suitable for the type of work you do and the hazards on the job.
2. Check whether the shoes have safety certificates and meet health and safety standards.
3. Regularly check the condition of shoes, look for damage, cracks, abrasions, peeling off elements.
4. Pay special attention to the condition of the sole, whether it is not worn, slippery or damaged.
5. Shoelaces should be tied and in good condition to prevent tripping.
6. If the shoes have metal elements (e.g. Toe cap), avoid working in places where there is a risk of electric shock.
7. When working with chemicals, make sure your shoes are resistant to these substances.
8. Do not use shoes for purposes other than those for which they are intended.
9. If your shoes get wet, dry them thoroughly before reuse to prevent the growth of fungi and bacteria.
10. Clean your shoes regularly, removing dirt and debris that can affect their protective properties.
11. Remember to replace your shoes with new ones as soon as you notice that they have lost their protective properties or are damaged.
12. Do not modify work boots, as changes can reduce their effectiveness.
13. Store your shoes in a dry and airy place to prevent damage.
14. Pay attention to the right size so that the shoes do not cause abrasions and discomfort during work.
15. When choosing shoes, pay attention to the breathability of the material so that the foot does not sweat excessively.
16. For work at height, choose shoes with a non-slip sole for added safety.

Producent — dane kontaktowe

Schmith Polska S.A.
ul. Wschodnia 8
83-110
Tczew
PL
biuro@schmith.pl