

Link do produktu: <https://www.strefainternetowa.com/schmith-kurtka-zimowa-rozmiar-l-zolta-p-1942.html>



SCHMITH KURTKA ZIMOWA ROZMIAR L ŻÓŁTA

Cena	199,99 zł
Numer katalogowy	ALP-18034093238
Kod producenta	S1150-L
Kod EAN	5902004739502

Opis produktu

■ KURTKA ZIMOWA KRÓTKA ROZMIAR. L

Szczegóły:

- Wodoodporna, oddychająca i wiatroszczelna kurtka zimowa.
- Podklejane szwy oraz powłoka PU zapewniają nieprzemakalność.
- Odpinany kaptur z regulacją głębokości i szerokości.
- Wewnętrzny kołnierz z polaru zapewnia ciepło i komfort dla szyi.
- Zapięcie na zamek błyskawiczny z dodatkową wewnętrzną listwą chroniącą przed wiatrem.
- Kieszonka na piersi zapinana na zamek błyskawiczny w kontrastowym kolorze, który ożywia kolor kurtki.
- Odblaskowe lamówki i taśmy z przodu i z tyłu dla bezpieczeństwa i ozdoby.
- Dodatkowe wewnętrzne elastyczne mankiety zapewniają ciepło i wygodę.
- Rękawy o ergonomicznym kształcie dopasowują się do naturalnych ruchów ramion.
- Dzięki regulacji dolnego obwodu kurtki za pomocą gumki i stoperów możliwe jest lepsze dopasowanie do sylwetki.
- Kurtka posiada łącznie aż 8 pojemnych kieszeni wewnątrz i na zewnątrz, w tym kieszenie z klapką, kieszenie zapinane na zamek błyskawiczny, kieszenie na telefon komórkowy, dokumenty oraz kieszenie z siatki.

Tkanina wierzchnia : 100% poliestr z powłoką PU - wodoodporna i oddychająca

Podszewka : 100% poliestr

Wypełnienie : ocieplina poliestrowa

Rozmiar

Obwód na wysokości pach

Długość na środku pleców

Długość rękawa od ramienia

S

52

74

65

M

56

76

67

L

60

78

69

XL

64

80

70

XXL

68

82

72

■ **DANE TECHNICZNE**

□ **PRODUCENT:**

S1150-L

L

60

78

69

□ **ROZMIAR:**

L

□ **TYP:**

Z kapturem

□ **JEDNOSTKA MIARY:**

szt.

Parametry produktu

- **Stan:** Nowy
- **Kod producenta:** S1150-L
- **Marka:** Schmith
- **Model:** S1150
- **Rozmiar:** L
- **Przeznaczenie:** uniwersalne
- **Typ:** kurtka
- **Sezon:** zima
- **Cechy dodatkowe:** odzież ocieplana, odzież odblaskowa, odzież wodoodporna
- **Kolor:** czarny
- **EAN (GTIN):** 5902004739502

Informacje o bezpieczeństwie

List of safety warnings for workwear and health and safety based on the requirements of Regulation (EU) 2023/988 on general product safety (GPSR): 1. Choosing the right size: * Make sure that the workwear is properly tailored to your figure. Too loose or too tight clothing can restrict freedom of movement and increase the risk of an accident. 2. Risk Assessment: * Before each use of workwear, carefully analyze the potential hazards occurring in the workplace. Make sure that the clothing you choose provides adequate protection against identified hazards (e.g. cutting, burns, chemicals). 3. Technical condition inspection: * Regularly check the technical condition of your workwear. Make sure that there is no damage, such as abrasions, tears, cracks, which could reduce its protective properties. If damage is found, clothing should be replaced immediately. 4. Maintenance and cleaning: * Follow the manufacturer's recommendations for the maintenance and cleaning of workwear. Improper cleaning can damage the material and reduce its protective properties. 5. Specialty clothing: * For work requiring specialized protection (e.g. welding, work with chemicals, work at height), use only workwear with appropriate certificates and meeting applicable standards. 6. Weather conditions: * Adapt your workwear to the prevailing weather conditions. In the case of low temperatures, use thermal insulation clothing, and in the case of high temperatures, breathable and moisture-wicking clothing. 7. Visibility: * In workplaces with limited visibility (e.g. road works, work near machines) use high-visibility workwear, equipped with reflective elements. 8. Tangle protection: * Avoid wearing loose workwear near moving parts of machinery and equipment. Loose clothing items can get tangled and cause a serious accident. 9. Usage training: * Make sure that you and your colleagues have been trained in the correct selection, use, maintenance and storage of workwear. 10. Storage: * Store your workwear in a dry and clean place, away from direct sunlight and heat sources. 11. Clothing replacement: * Replace your workwear regularly, even if it shows no visible damage. Over time, materials may lose their protective properties.

Producent — dane kontaktowe

Schmith Polska S.A.
ul. Wschodnia 8
83-110
Tczew
PL
biuro@schmith.pl