

Link do produktu: <https://www.strefainternetowa.com/schmith-preparat-do-wiercenia-i-gwintowania-400ml-p-603.html>



SCHMITH PREPARAT DO WIERCENIA I GWINTOWANIA 400ML

Cena	29,99 zł
Numer katalogowy	ALP-18877306622
Kod producenta	S0201-400
Kod EAN	5902004763347

Opis produktu

PREPARAT DO WIERCENIA I GWINTOWANIA 400ML

Schmith S0201-400

Wolno odparowujący zmywacz, który efektywnie czyści i odtłuszcza elementy z wszelkich zabrudzeń. Dzięki zastosowaniu nowoczesnej formuły łączącej najsilniejsze substancje aktywne, preparat skutecznie usuwa woski, oleje, smary, środki ochrony czasowej, pozostałości po klejach, błyskawicznie przy tym odparowując.

- nie zawiera acetonu
- neutralny wobec gumy
- nadaje się do czyszczenia powierzchni przed klejeniem i malowaniem
- czyści elementy układów hamulcowych i sprzęgieł
- usuwa powłoki ochronne z tarcz hamulcowych, powłoki antykorozyjne z form wtryskowych, sadzę oraz uporczywe zabrudzenia
- silny strumień skutecznie wypłukujący zanieczyszczenia
- ładny zapach nieutrudniający pracy
- znajduje zastosowanie w przemyśle hutniczym, stoczniowym, wydobywczym, poligraficznym, motoryzacyjnym, chemicznym

Parametry produktu

- **Stan:** Nowy
- **Kod producenta:** S0201-400
- **Marka:** Schmith
- **Liczba elementów w zestawie:** 1
- **Waga produktu z opakowaniem jednostkowym:** 0.6
- **Kod taryfy celnej:** 34029090
- **EAN (GTIN):** 5902004763347

Informacje o bezpieczeństwie

List of safety warnings for metalworking based on the requirements of General Product Safety Regulation (EU) 2023/988

(GPSR): 1. Vision hazard: * Wear safety glasses or face shield during metalworking to protect your eyes from chipping, sparks and material particles. 2. Hearing Hazard: * Use hearing protectors when the noise level exceeds the acceptable standards to avoid permanent hearing damage. 3. Respiratory hazard: * Wear a dust mask or respirator to avoid inhaling harmful dust and fumes generated during processing. * Provide adequate ventilation in the workplace to minimize the concentration of harmful substances in the air. 4. Hazard to hands and skin: * Wear protective gloves to protect hands from cuts, burns and chemicals. * Use a protective cream on the skin to protect it from dryness and irritation. 5. Hazard of clothing: * Wear appropriate workwear that protects the body from sparks, chipping and other hazards. * Avoid loose clothing, jewelry, and long hair that can be pulled in by machines. 6. Fire hazard: * Keep your work area free of flammable materials such as paper, cardboard and chemicals. * Have access to the fire extinguisher and know how to use it in case of fire. 7. Electrical hazard: * Check the technical condition of electrical equipment and wires before use. * Avoid working with electrical appliances in humid conditions. * Disconnect devices from power during maintenance and repairs. 8. Hazard associated with machinery and tools: * Check the technical condition of machinery and tools before use. * Use machinery and tools according to the instruction manual and safety rules. * Regularly maintain and sharpen tools. * Do not use damaged machinery or tools. * Use shields and protections on machines. 9. Material handling hazard: * Use suitable lifting and handling equipment for heavy materials. * Follow the principles of ergonomics when lifting and moving materials. 10. Hazards associated with chemicals: * Store chemicals in appropriate containers and places. * Use chemicals according to instructions and safety rules. * Ensure adequate ventilation when working with chemicals. 11. Other hazards: * Keep your workplace tidy. * Provide adequate lighting in the workplace. * Train employees in occupational health and safety. * Carry out security checks regularly. * Comply with all applicable health and safety regulations.

Producent — dane kontaktowe

Schmith Polska S.A.
ul. Wschodnia 8
83-110
Tczew
PL
biuro@schmith.pl