

Link do produktu: <https://www.strefainternetowa.com/sciernica-listkowa-cyrkonowa-wypukla-40-p-1867.html>



Ściernica listkowa cyrkonowa wypukła 40

Cena	6,09 zł
Numer katalogowy	ALP-18051469309
Kod producenta	SSLC-01
Kod EAN	5902004722603

Opis produktu

■ ŚCIERNICA LISTKOWA CYRKONOWA WYPUKŁA 40

Ściernica listkowa, ściernica cyrkonowa, kształt wypukły do szlifowania pod kątem do 15°.

- Przeznaczona do stali, stali nierdzewnych, metali nieżelaznych
- Nadaje się do obróbki - szlifowanie zgrubne i dokładne, szlifowanie spawów, usuwanie rdzy, czyszczenie
- Wypukła, średnica 125 mm.

■ DANE TECHNICZNE

▣ PRODUCENT:

▣ SYMBOL / KOD:	SSLC-01
▣ ŚREDNICA:	125 mm.
▣ DŁUGOŚĆ:	-
▣ SZEROKOŚĆ:	-
▣ ROZMIAR:	-
▣ OBJĘTOŚĆ:	-
▣ UCHWYT / MOCOWANIE:	-
▣ TYP:	granulacja 40, wypukła
▣ JEDNOSTKA MIARY:	szt.

▣ ILOŚĆ SPRZEDAŻOWA:	10 szt.
▣ ILOŚĆ W OPAKOWANIU:	20 szt.
▣ KOD EAN:	5902004722603

Parametry produktu

- **Stan:** Nowy
- **Marka:** Schmith
- **Kod producenta:** SSLC-01
- **Waga produktu z opakowaniem jednostkowym:** 0.1
- **Rodzaj tarczy:** ścierna
- **Średnica otworu:** 22,2mm
- **Średnica tarczy:** 125mm
- **Seria:** S
- **EAN (GTIN):** 5902004722603

Informacje o bezpieczeństwie

List of safety warnings for metalworking based on the requirements of General Product Safety Regulation (EU) 2023/988 (GPSR): 1. Vision hazard: * Wear safety glasses or face shield during metalworking to protect your eyes from chipping, sparks and material particles. 2. Hearing Hazard: * Use hearing protectors when the noise level exceeds the acceptable standards to avoid permanent hearing damage. 3. Respiratory hazard: * Wear a dust mask or respirator to avoid inhaling harmful dust and fumes generated during processing. * Provide adequate ventilation in the workplace to minimize the concentration of harmful substances in the air. 4. Hazard to hands and skin: * Wear protective gloves to protect hands from cuts, burns and chemicals. * Use a protective cream on the skin to protect it from dryness and irritation. 5. Hazard of clothing: * Wear appropriate workwear that protects the body from sparks, chipping and other hazards. * Avoid loose clothing, jewelry, and long hair that can be pulled in by machines. 6. Fire hazard: * Keep your work area free of flammable materials such as paper, cardboard and chemicals. * Have access to the fire extinguisher and know how to use it in case of fire. 7. Electrical hazard: * Check the technical condition of electrical equipment and wires before use. * Avoid working with electrical appliances in humid conditions. * Disconnect devices from power during maintenance and repairs. 8. Hazard associated with machinery and tools: * Check the technical condition of machinery and tools before use. * Use machinery and tools according to the instruction manual and safety rules. * Regularly maintain and sharpen tools. * Do not use damaged machinery or tools. * Use shields and protections on machines. 9. Material handling hazard: * Use suitable lifting and handling equipment for heavy materials. * Follow the principles of ergonomics when lifting and moving materials. 10. Hazards associated with chemicals: * Store chemicals in appropriate containers and places. * Use chemicals according to instructions and safety rules. * Ensure adequate ventilation when working with chemicals. 11. Other hazards: * Keep your workplace tidy. * Provide adequate lighting in the workplace. * Train employees in occupational health and safety. * Carry out security checks regularly. * Comply with all applicable health and safety regulations.

Producent — dane kontaktowe

Schmith Polska S.A.
ul. Wschodnia 8
83-110
Tczew
PL
biuro@schmith.pl