Dane aktualne na dzień: 27-10-2026 21:15

Link do produktu: https://www.strefainternetowa.com/sciernica-z-trzpieniem-60x30mm-p100-p-1881.html

# Ściernica z trzpieniem 60x30mm P100

| | |
|---|---|
| Cena | **5,96 zł** |
| Numer katalogowy | **ALP-18043344741** |
| Kod producenta | **SSZT2-100** |
| Kod EAN | **5902004750071** |

## Opis produktu

Ściernica z trzpieniem 60x30mm P100

Symbol: SSZT2-100

Do obróbki elementów profilowanych, powierzchni wewnętrznych, wąskich i trudno dostępnych miejsc. Do szlifowania radialnego. Do obróbki drewna, metali, tworzywa sztucznego.

zastosowanie: do szlifowania - stal, żeliwo, farby lakiery szpachle, drewno, skóra, tworzywa sztuczne,

nasyp: elektrokorund

mocowanie: trzpień

średnica: 60 mm

grubość: 30 mm

granulacja : 100

## Parametry produktu

- **Stan:** Nowy
- **EAN (GTIN):** 5902004750071
- **Kod producenta:** SSZT2-100
- **Marka:** Schmith
- **Rodzaj tarczy:** ścierna

## Informacje o bezpieczeństwie

List of safety warnings for metalworking based on the requirements of General Product Safety Regulation (EU) 2023/988 (GPSR): 1. Vision hazard: * Wear safety glasses or face shield during metalworking to protect your eyes from chipping, sparks and material particles. 2. Hearing Hazard: * Use hearing protectors when the noise level exceeds the acceptable standards to avoid permanent hearing damage. 3. Respiratory hazard: * Wear a dust mask or respirator to avoid inhaling harmful dust and fumes generated during processing. * Provide adequate ventilation in the workplace to minimize the concentration of harmful substances in the air. 4. Hazard to hands and skin: * Wear protective gloves to protect hands from cuts, burns and chemicals. * Use a protective cream on the skin to protect it from dryness and irritation. 5. Hazard of clothing: * Wear appropriate

workwear that protects the body from sparks, chipping and other hazards. * Avoid loose clothing, jewelry, and long hair that can be pulled in by machines. 6. Fire hazard: * Keep your work area free of flammable materials such as paper, cardboard and chemicals. * Have access to the fire extinguisher and know how to use it in case of fire. 7. Electrical hazard: * Check the technical condition of electrical equipment and wires before use. * Avoid working with electrical appliances in humid conditions. * Disconnect devices from power during maintenance and repairs. 8. Hazard associated with machinery and tools: * Check the technical condition of machinery and tools before use. * Use machinery and tools according to the instruction manual and safety rules. * Regularly maintain and sharpen tools. * Do not use damaged machinery or tools. * Use shields and protections on machines. 9. Material handling hazard: * Use suitable lifting and handling equipment for heavy materials. * Follow the principles of ergonomics when lifting and moving materials. 10. Hazards associated with chemicals: * Store chemicals in appropriate containers and places. * Use chemicals according to instructions and safety rules. * Ensure adequate ventilation when working with chemicals. 11. Other hazards: * Keep your workplace tidy. * Provide adequate lighting in the workplace. * Train employees in occupational health and safety. * Carry out security checks regularly. * Comply with all applicable health and safety regulations.

## Producent — dane kontaktowe

Schmith Polska S.A.
ul. Wschodnia 8
83-110
Tczew
PL
biuro@schmith.pl