

Link do produktu: <https://www.strefainternetowa.com/stalco-wiertlo-do-drewna-lopatkowe-plaskie-35x152mm-s-72037-p-3463.html>

STALCO WIERTŁO DO DREWNA ŁOPATKOWE PŁASKIE 35x152mm S-72037



Cena	28,00 zł
Numer katalogowy	ALP-15226358790
Kod producenta	72035
Kod EAN	5901466141472

Opis produktu

WIERTŁO DO DREWNA PŁASKIE 32x152mm STALCO PERFECT S-72035

- Wiertło do wykonywania głębokich otworów w drewnie, kantówkach, materiałach drewnopochodnych i płytach MDF.
- Uchwyt wiertła łopatkowego sześciokątny.
- Wierzchołek i ostrze szlifowane dla precyzyjnego centrowania.
- Średnica 32mm
- Długość całkowita 152 mm

Wiertła płaskie zwane również wiertłami piórowymi -są to wiertła o płaskim kształcie, zakończone szpikulcem centrującym, ich główną zaletą jest możliwość wykonywania otworów w drewnie o większych średnicach niż przy pomocy zwykłych wiertel.

Parametry produktu

- **Stan:** Nowy
- **Marka:** Stalco
- **Kod producenta:** 72035
- **Rodzaj wiertła:** piórkowe
- **Typ mocowania:** sześciokątny
- **Zastosowanie:** do drewna
- **EAN (GTIN):** 5901466141472

Informacje o bezpieczeństwie

List of drill safety warnings based on the requirements of Regulation (EU) 2023/988 on General Product Safety (GPSR): 1. Risk of injury: * Use the drill according to the instruction manual of the power tool. * Before replacing the drill, disconnect the power tool from the power supply. * Do not use damaged drill bits, they may break during operation. * Always use safety glasses and gloves to protect your eyes and hands. 2. Risk of fire or explosion: * Do not use drills near flammable or explosive materials. * Make sure the drill bit is properly fixed in the drill holder. 3. Risk of hearing injury: * Use hearing protectors when working with power tools. 4. Risk of dust inhalation: * Use a dust mask when drilling to avoid inhaling harmful dust. 5. Workplace safety: * Keep your workplace tidy. * Provide adequate lighting. * Do not use power tools in damp rooms. * Store drill bits in a safe place, out of reach of children. 6. Power tool overload: * Do not overload the power tool, use the appropriate

pressure force. 7. Grounding: * Make sure the power tool is properly grounded if the structure requires it. 8. Power supply: * Check that the power supply voltage complies with the requirements of the power tool.

Producent — dane kontaktowe

STALCO
Ofiar Katynia 1
32-050
SKAWINA
PL
centrala@stalco.pl
696113253